

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/07/2022

Submitted Date:

07/07/2022

Document Number:

693507507

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 318765 _____ Silver, Randy _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: _____ 46290 _____
 Name of Operator: KP KAUFFMAN COMPANY INC _____
 Address: 1700 LINCOLN ST STE 4550 _____
 City: _____ DENVER _____ State: _____ CO _____ Zip: _____ 80203 _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- _____ 5 _____ Number of Comments
 _____ 1 _____ Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
,		dnr_cogccenforcement@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242122	WELL	SI	03/01/2022	OW	123-09913	UPRR 43 PAN AM I 27	PA

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: Well is P&A surface equipment on site

Corrective Action: Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. All access roads to plugged and abandoned wells and associated production facilities shall be closed, graded and recontoured. Culverts and any other obstructions that were part of the access road(s) shall be removed. Well locations, access roads and associated facilities shall be reclaimed

Date: 09/13/2021

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Pump Jack # 0

Comment:

Corrective Action:

Date:

Type: Ancillary equipment # 1

Comment: Electric panel

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 242122 Type: WELL API Number: 123-09913 Status: SI Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday June 7 2022 at approximately 09:08AM, I, Inspector Randy Silver, Conducted an on-site re-inspection per Doc#'s 693505434 and 693505573. Location: UPRR 43 Pan AM I19 Operator: KP Kauffman API#:12309039 County: Weld While there, I observed P&A well site During this inspection the following possible compliance issues were observed: P&A operations: Rule 1004a Corrective action date of 9-13-21 See photos 1,2 This is the Third inspection with said violation. At time of inspection it appears no activity has taken place on site. Weather conditions: Dry and cloudy. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	07/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507508	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5797392