

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2022

Submitted Date:

07/11/2022

Document Number:

699105678**FIELD INSPECTION FORM**Loc ID 459550 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459560	WELL	PR	01/10/2022	OW	123-48948	Guttersen D09-765	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil in multiple spots needs to be removed. See attached photos		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: 07/22/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 459560 Type: WELL API Number: 123-48948 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 01/20/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 7 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
 On Monday 7/11/22 at approximately 0926hrs, I, Inspector Adam Burns,  
 Conducted an on-site inspection at Gutteresen D09-765 of Chevron, at  
 API # 05-123-48948 in Weld County, Colorado.  
 During this inspection the following possible compliance issues were observed:  
 Stained soil in multiple spots needs to be removed. "Properly dispose of oily waste in  
 accordance with 905.e." With a corrective action date of 7/22/22  
 See attached photos.  
 Submit pictures on FIRR.  
 A follow up on this site inspection needs to be conducted to ensure the  
 compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

burnsa

07/11/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699105679	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800124">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800124</a>