




OLORADO OIL AND GAS CONSERVATION COMMISSION
SUNDRY NOTICES AND REPORTS OF WELLS



(Indicate nature of data by checking below)

Notice of intention to drill (attach plat) _____
 Notice of intention to change plans _____
 Notice of date for test of water shut-off _____
 Report on result of test of water shut-off _____
 Notice of intention to re-drill or repair well _____
 Notice of intention to clean out well _____
 Statement of shooting _____
 Statement of perforating _____
 Notice to pull or otherwise alter casing _____
 Notice of intention to abandon well _____ X
 Report of work done on well since previous report _____

OIL & GAS
CONSERVATION COMMISSION
Locate Well Correctly

		4	
			o

Notice to do work ☐
 Report of work done ☒

Land: Fee and Patented ☒
 State ☐

Lease No. _____

COLORADO

State

ADAMS

County

BUSY BEE

Field

1 (Well No.) SCHTUL (Lease) SE (1/4 Sec.) 4 (Sec.) T3S (Twp.) R60W (Range) 6th P.M. (Meridian)

The Well is located 660 Ft. (N) of Section Line and 652 Ft. (E) of Section Line. SE $\frac{1}{4}$ SE $\frac{1}{4}$ (S) (W)

The elevation above sea level is 5,012 Ft. K.B.

Details of Plan of Work: (State names of and expected depths to objective sands. Show sizes, weights, and length of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work.)

The Jeff Hawks Schtul No. 1 was plugged and abandoned on June 21, 1956 at a total depth of 6,571 feet as follows:

6,400 - 6,550 feet with 50 sacks
 80 - 110 feet with 15 sacks
 0 - 10 feet with 10 sacks

AJJ	
DVR	
FJK	
WRS	✓
HHH	
AMH	
JUD	✓
FILE	

Approved: JUL 5 1956

A. J. Perin
 Director

Date June 26, 1956

Company CARMACK DRILLING CO.

Address 1008 Mile High Center
 Denver 2, Colorado

By [Signature]

Title Manager of Exploration

Submit reports of proposed work, for approval, on this form in Duplicate for patented lands and in Triplicate for school and state lands.