

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/27/2022

Submitted Date:

07/28/2022

Document Number:

701103376**FIELD INSPECTION FORM**Loc ID 314913 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 760 HORIZON DRIVE STE 400City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gas, UtahGasCorp	970-693-6021	inspections@utahgascorp.com	Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229882	WELL	PR	07/01/2021	GW	103-07540	FEDERAL 17-2	PR

General Comment:

COGCC Routine Inspection Report Summary

Location is in a High Priority Habitat Area.

During this inspection the following compliance issues were observed:

- No Api # on battery sign.
 - Storm water inspection not fully conducted due to rainstorm moving in on location. In photo of metershed it was noticed that there is some stormwater damage on edge of location.
- A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No Api # on battery sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	09/30/2022

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 229882	Type: WELL	API Number: 103-07540	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		

Comment: Storm water inspection not fully conducted due to rainstorm moving in on location. In photo of metershed it was noticed that there is some stormwater damage on edge of location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403120249	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5815277
701103377	Inspection 701103376 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5815275