

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:

Type	WEEDS		
Comment:	Overgrown weeds inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	09/01/2022

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 243187 Type: WELL API Number: 123-10978 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679604331. One out of two previous corrective actions assigned to this location have been resolved. Unable to identify if the other previous corrective action was resolved. Standing water is surrounding the wellhead casing. One new corrective action was observed at the time of re-inspection. Please review narrative below for more information.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, wet ground On Thursday, August 18, 2022 at approximately 09:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at BUNN 1-35 (PDC Energy), at location #: 319270 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. Over grown weeds surrounding wellhead inside fencing. Remove to comply with Rule 606. (Corrective Action Date: September 1, 2022) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	08/18/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604964	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833562