

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Overgrown weeds inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 606.		Date: <u>09/01/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift # 1			
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 243187 Type: WELL API Number: 123-10978 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679604331. One out of two previous corrective actions assigned to this location have been resolved. Unable to identify if the other previous corrective action was resolved. Standing water is surrounding the wellhead casing. One new corrective action was observed at the time of re-inspection. Please review narrative below for more information.</p> <p>COGCC Inspection Report Summary **Weather Conditions: sunny, wet ground On Thursday, August 18, 2022 at approximately 09:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at BUNN 1-35 (PDC Energy), at location #: 319270 in WELD COUNTY Colorado. While there, I observed a shut in wellhead. During this inspection the following possible compliance issues were observed: 1. Over grown weeds surrounding wellhead inside fencing. Remove to comply with Rule 606. (Corrective Action Date: September 1, 2022) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	08/18/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403140958	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833578
679604964	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5833562