

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403110131

Date Received:
07/19/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Tammy Jones</u>	<u>505-324-5185</u>	<u>FarmingtonRegulatoryTechs@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500244
Inspection Date: 07/18/2022 FIR Submit Date: 07/19/2022 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 312037

Location Name: SCHUYLER 34-9-M34N9W Number: 30NWSE County: LA PLATA
Qtrqtr: NWSE Sec: 30 Twp: 34N Range: 9W Meridian: M
Latitude: 37.158530 Longitude: -107.865030

FACILITY - API Number: 05-067- -00 Facility ID: 216505

Facility Name: SCHUYLER 34-9 Number: 30-2
Qtrqtr: NWSE Sec: 30 Twp: 34N Range: 9W Meridian: M
Latitude: 37.158530 Longitude: -107.865030

CORRECTIVE ACTIONS:

1 ☒ CA# 163416

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 07/19/2022

Response: CA COMPLETED Date of Completion: 07/19/2022

Operator Comment: Securely tightened all leaking production equipment.

COGCC Decision: Approved

COGCC
Representative:

CA from previous inspection Doc# 702500244 has been satisfactorily completed.

2 ☒ CA# 163417

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/28/2022

Response: CA COMPLETED

Date of Completion: 07/19/2022

Operator
Comment:

Removed all impacted material around the wellhead and properly disposed of it.

COGCC Decision: Approved

COGCC
Representative:

CA from previous inspection Doc# 702500244 has been satisfactorily completed.

3 ☒ CA# 163418

Corrective Action: Install sign to comply with Rule 605.h.

Date: 08/18/2022

Response: CA COMPLETED

Date of Completion: 07/19/2022

Operator
Comment:

Took off the deteriorated sticker and painted the 286 bbl on the tank.

COGCC Decision: Approved

COGCC
Representative:

CA from previous inspection Doc# 702500244 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: All issues of concern have been resolved - see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 7/19/2022 1:22:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403110131	FIR RESOLUTION SUBMITTED
403110140	Resolved photos

Total Attach: 2 Files