

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2022

Submitted Date:

09/02/2022

Document Number:

702800642**FIELD INSPECTION FORM**Loc ID 313136 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 27742Name of Operator: EOG RESOURCES INCAddress: P O BOX 4362City: HOUSTON State: TX Zip: 77210-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		jennifer_yu@eogresources.com	
Wescoat, Cally	(303) 262-9973	cally_wescoat@eogresources.com	
Opp, Tracy	(303) 262-9469	tracy_opp@eogresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
313136	LOCATION	CL			-	FORT REYNOLDS STATE-612N92W 36SWSW	RI

General Comment:

On 08/29/2022, Reclamation Specialist O'Malley conducted a Final Reclamation and Stormwater inspection at EOG Resources Inc's Fort Reynolds State-612N92W /36SWSW Location #313136 in Moffat County, Colorado.

The following compliance issues were observed during this inspection:

- Location access road remains
- Stormwater: gully erosion

Refer to the "Reclamation" and "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____ Pass

Debris removed _____ Pass No disturbance /Location never built _____

Access Roads _____ Regraded **Fail** Contoured **Fail** Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Pass Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control **Fail**

Non cropland: Revegetated 80% _____ In _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____ Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

This location does not meet reclamation requirements; access road remains. The Location access road has not been adequately reclaimed. Vegetation growth is absent in tire tracks where soils are compacted and bare. Vehicles appear to be utilizing the road, preventing revegetation. The access road must be reclaimed per Rule 1004.a.

At the time of this inspection vegetation on the Location is progressing towards 1004 standards. The Location is dominated by native perennial grasses, however, current vegetative cover does not appear adequate to stabilize the site. Refer to the "Stormwater" section of this inspection report.

Corrective Action:

Comply with 1004 Rules.

Date 11/15/2022

Conduct additional reclamation in accordance with COGCC 1000 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels on the Location and access road. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 11/15/2022.

Overall Final Reclamation **Fail**Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Insufficient stormwater and sediment control BMPs in place; there is a gully present at the south of the Location. Current vegetative cover on the Location does not appear to be sufficient to stabilize the site. Long-term stabilization of the site is required to receive a passing final inspection.

Corrective Action:

Comply with 1002.f. Implement and maintain stormwater and erosion control BMPs until long-term stabilization has been achieved and site has received a passing final reclamation inspection.

Date: 11/15/2022Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
702800643	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5847521