

OIL AND GAS CONSERVATION COMMISSION DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

00278635

RECEIVED

DEC 31 1970

5. LEASE DESIGNATION AND SERIAL NO.
COLO. OIL & GAS CONS. COMM.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

12. COUNTY

13. STATE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

At proposed prod. zone

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work

August 15, 1970

Late

Moved in, rigged up, prepared to abandon well. Run sand from 5582 to 5560. Dumped five sacks cement to 5512. Shot at 45 hundred, didn't come loose, worked pipe, spotted oil, shot at 4010. Didn't come loose, spotted oil & water, shot at 3525, Come out of hole. Mudded hole to 213 ft set 15 sacks cement from 213 ft to 163 ft. Mudd hole to 30 ft. Set 10 sacks cement 3 ft below ground level. Weld on cap.

DVR	
FJP	<input checked="" type="checkbox"/>
HHM	
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>

Ex Oil Prod.

18. I hereby certify that the foregoing is true and correct

SIGNED Mark SnowdenTITLE ownerDATE 12/29/70

(This space for Federal or State office use)

APPROVED BY W. RogersTITLE D & G CONS. COMM.DATE JAN 6 1971

CONDITIONS OF APPROVAL, IF ANY:

New oper - Snowden - plugged