

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403172108

Date Received:

09/20/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

RangelyRegulatory@scoutep.com

Patterson, Chris
Chris.Patterson@scoutep.com

Sanford, Anita
Anita.Sanford@scoutep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204073

Inspection Date: 09/12/2022

FIR Submit Date: 09/13/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314707

Location Name: F V LARSON B-62N102W Number: 26SESE County: _____

Qtrqr: SESE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.110390 Longitude: -108.805620

FACILITY - API Number: 05-103-00 Facility ID: 314707

Facility Name: F V LARSON B-62N102W Number: 26SESE

Qtrqr: SESE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.110390 Longitude: -108.805620

CORRECTIVE ACTIONS:

1 CA# 164528

Corrective Action: Comply with Rules 1004.e and 606.c. Continue to monitor and manage weeds until Location receives a passing final reclamation inspection.

Date: 09/20/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Weeds removed and will be spayed in the spring

COGCC Decision: _____

COGCC
Representative:

3 CA# 164530

Corrective Action:

Comply with Rule 1002.f; install and maintain stormwater and erosion control measures; if it is determined that a specific BMP is insufficient to mitigate degradation on a site, cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should be considered and applied, or used in conjunction. Upon completion of additional reclamation efforts, ensure BMPs are implemented to stabilize the seeded soils and to prevent weed establishment.

Date: 09/20/2022

Continue to monitor and manage stormwater until Location receives a passing final reclamation inspection.

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator
Comment:

Addition BMPs installed

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

Please see attached PICs

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Sr HSE Coordinator

Date: 9/20/2022 3:48:52 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403172200	PIC
403172201	PIC

Total Attach: 2 Files