

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403152570

Date Received:

08/31/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10734

Name of Operator: HIGH RIVER RESOURCES OPERATING LLC

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Archuleta, Amy</u>		<u>aarchuleta@highriverllc.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Mickey Ahrens</u>		<u>mahrens@highriverllc.com</u>
<u>Vaughn, Robert</u>		<u>rvaughn@highriverllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500353

Inspection Date: 08/29/2022

FIR Submit Date: 08/30/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HIGH RIVER RESOURCES OPERATING LLC

Company Number: 10734

Address: 3838 OAK LAWN AVE SUITE 710

City: DALLAS State: TX Zip: 75219

LOCATION - Location ID: 333517

Location Name: BONDAD 34-10-M34N10W Number: 36NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144740 Longitude: -107.881780

FACILITY - API Number: 05-067-00 Facility ID: 214279

Facility Name: BONDAD 34-10 Number: 1-36

Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M

Latitude: 37.144740 Longitude: -107.881780

CORRECTIVE ACTIONS:

1 ☒ CA# 164209

Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).

Date: 09/29/2022

Response: CA COMPLETED

Date of Completion: 08/31/2022

The metal secondary containment has been repaired.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative: CA from previous inspection Doc# 702500353 has been satisfactorily completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: The ball valve handle was also removed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: \_\_\_\_\_

Title: Regulatory Supervisor

Date: 8/31/2022 10:54:31 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403152570	FIR RESOLUTION SUBMITTED
403152702	Secondary Cont Repair - Debris removal

Total Attach: 2 Files