



99999999

CONSERVATION COMMISSION
STATE OF COLORADOFile for Patented and Federal lands.
File in triplicate for State lands.

NOV 20 1978

AP10758128

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Ramrod

9. WELL NO.

4-2

10. FIELD AND POOL, OR WILDCAT

Ramrod

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 33-12N-55W

12. COUNTY OR PARISH 13. STATE

Logan

Colorado

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Petroleum, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 60, Casper, WY 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

700' FNL 1995' FEL C/ NW NE

At proposed prod. zone

Same

14. PERMIT NO.

69-200

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4549 KB

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON

CHANGE PLANS

☐
☐
☒
☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

☐
☐
☐

REPAIRING WELL

ALTERING CASING

ABANDONMENT

☐
☐
☐(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to plug & abandon well - Economically infeasible to operate - will proceed when approval received.

PLUGGING INSTRUCTIONS:

1. Run sand over perforations plus 5 sacks cement on top of sand.
2. Cut and pull pipe.
3. Run 15 sacks cement plug at base of surface casing.
4. Run 5 sacks plug at surface with a welded steel plate on the stub; cut off 3 feet below the surface.

SIGNED A. J. JuliusTITLE District Production Supt.DATE Nov. 16, 1978

(This space for Federal or State office use)

DIRECTOR

D & D CONS. CORP.

APPROVED BY W. L. Rogers

TITLE

DATE NOV 20 1978

CONDITIONS OF APPROVAL, IF ANY:

DVR	
FJP	
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
RLS	
CGM	



00245335