

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/11/2022

Submitted Date:

10/11/2022

Document Number:

707900059

FIELD INSPECTION FORM
 Loc ID 422357 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 44390

Name of Operator: JAVERNICK OIL

Address: 3040 E MAIN

City: CANON CITY State: CO Zip: 81212

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422358	WELL	SI	11/01/2020	OW	043-06204	CHANDLER CREEK 22-32	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	No well head sign at well head.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	11/11/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around well head and load lines at tank battery		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	11/11/2022
Type	WEEDS		
Comment:	Weeds around well head and in tank Battery containment		
Corrective Action:	Comply with rule 606	Date:	11/11/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link fence in disrepair need to reinstall or remove.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	Guy line anchors not Properly marked.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	11/11/2022
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CRUDE OIL	1	300 BBLs	STEEL AST		38.352987,-105.136813	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:	Performed FLIRR inspection did not observe any violations					
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected FacilitiesFacility ID: 422358 Type: WELL API Number: 043-06204 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well. Well has not produced since 10-1-20.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 11/11/2022**BradenHead**Date of Last Brhd Test: 02/21/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary
 On Tuesday October 11, 2022 at approximately 2:15PM, I, Inspector Randy Silver, conducted an on-site inspection.
 Location: Chandler Creek #22-32
 Operator: Javernick Oil
 API#: 043-06204
 County: Fremont
 While there, I observed a SI well site.
 During this inspection the following possible compliance issues were observed:
 Signs: Rule 605a Corrective action date of 11-11-22 See photos.
 Stained soil: Rule 905 e Corrective action date of 11-11-22 See Photos 2,3,7
 Guy line anchors: Rule 1003 Corrective action date of 11-11-22 See photo5
 MIT : Rule 417 b Corrective action date of 11-11-22
 Weeds: Rule 606 Corrective action date of 11-11-22 See photos 4,8
 Well head sign: Rule 605a Corrective action date of 11-11-22 See photo1
 Weather conditions: Clear
 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

silverr

10/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900060	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883649