

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403201692

Date Received:  
10/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10661

Name of Operator: CIVITAS NORTH LLC

Address: 518 17TH STREET #3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Mike Storey

970-939-6353

mstorey@civiresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696304437

Inspection Date: 09/19/2022

FIR Submit Date: 09/20/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 476815

Location Name: Allred 8-59 Number: 30 County: \_\_\_\_\_

Qtrqr: NENW Sec: 30 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.638789 Longitude: -104.021999

FACILITY - API Number: 05-123-00 Facility ID: 476815

Facility Name: Allred 8-59 Number: 30

Qtrqr: NENW Sec: 30 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.638789 Longitude: -104.021999

CORRECTIVE ACTIONS:

1 CA# 164660

Corrective Action: Comply with Rule 606

Date: 10/21/2022

Response: CA COMPLETED

Date of Completion: 10/18/2022

Operator  
Comment:

Unused equipment has been removed in compliance with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 164661

Corrective Action: Install sign to comply with Rule 605.h.

Date: 10/21/2022

Response: CA COMPLETED

Date of Completion: 10/18/2022

Operator  
Comment: Signs have been installed in compliance with Rule 605.h.

COGCC Decision:

COGCC  
Representative:

3 CA# 164662

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) per Rule 902.b

Date: 10/05/2022

Response: CA COMPLETED

Date of Completion: 10/18/2022

Operator  
Comment: Wildlife protection equipment has been installed in compliance with Rule 902.b.

COGCC Decision:

COGCC  
Representative:

4 CA# 164663

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."

Date: 10/05/2022

Response: CA COMPLETED

Date of Completion: 10/18/2022

Operator  
Comment: Oily waste has been removed in accordance with 905.e

COGCC Decision:

COGCC  
Representative:

5 CA# 164664

Corrective Action: Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b

Date: 10/05/2022

Response: CA COMPLETED

Date of Completion: 10/18/2022

Operator  
Comment: Wildlife protection equipment has been installed in compliance with Rule 902.b.

COGCC Decision:

COGCC  
Representative:

Corrective Action: Comply with Rule 606Date: 10/21/2022Response: CA COMPLETEDDate of Completion: 10/18/2022Operator  
Comment: Unused equipment has been removed in compliance with Rule 606.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory AnalystDate: 10/19/2022 8:32:23 AM**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

403201708	Inspection Photos
-----------	-------------------

Total Attach: 1 Files