

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2022

Submitted Date:

10/19/2022

Document Number:

693805224**FIELD INSPECTION FORM**Loc ID 322398 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 51130Name of Operator: LOCIN OIL CORPORATIONAddress: 600 TRAVIS ST STE 6161City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Arnim, Rees	713-469-0275	rarnim@locin.energy	Director of Engineering
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210410	WELL	PR	04/01/2021	GW	045-06166	FEDERAL 29-5	PR

General Comment:

COGCC staff performed a routine field inspection on 10/18/2022.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Access			
comment:	Bunniger Rd			
Corrective Action	L		Date:	
Type	Main			
comment:	Garfield Co Rd 201			
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign not updated to reflect current operator			
Corrective Action:	Install sign to comply with Rule 605		Date:	11/19/2022
Type	TANK LABELS/PLACARDS			
Comment:	Sign not updated to reflect current operator			
Corrective Action:	Install sign to comply with Rule 605		Date:	11/19/2022
Emergency Contact Number:				
Comment:	Sign not updated to reflect current operator			
Corrective Action:	Install sign to comply with Rule 605			Date: 11/19/2022
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PIT			
Comment:	Dehydrator blowdown pit			
Corrective Action:			Date:	
Equipment:				
			corrective date	
Type: Flow Line	# 1			
Comment:	Unused Flowine riser not blind flanged.			
Corrective Action:	Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.		Date:	11/24/2022
Type: Bradenhead	# 1			
Comment:				
Corrective Action:			Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter calibrated 5/25/22		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	STEEL AST		39.425612,-109.021344	
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.					
Corrective Action:	Install sign to comply with Rule 605.h.				Date:	11/19/2022

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		39.425691,-109.021236
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 11/19/2022

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 210410	Type: WELL	API Number: 045-06166	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PLunger lift			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 39.425692Long: -109.021066Reference Point: SE

Other: _____

Length: 20Width: 20**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:Fencing Type: Netting/Fence comFencing Condition: Adequate

Comment:

Corrective

Date:

Netting:Netting Type: Fence/Net ComboNetting Condition: Good

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation: NO2+ feet Freeboard: YES

Comment:

Corrective

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693805231	Inspection photos 10/18/2022	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891298