

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403197253

Date Received:

10/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10417

Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Hart, Tim

303-999-5420

thart@axpenergy.com

Harkins, Liz

719-429-4513

lharkins@fremontpetroleum.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 707900052

Inspection Date: 10/11/2022

FIR Submit Date: 10/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: INCREMENTAL OIL & GAS (FLORENCE) LLC

Company Number: 10417

Address: 113 N SANTA FE AVE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 322234

Location Name: RAINBOW-619S69W Number: 20NESW County: FREMONT

Qtrqr: NESW Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.379078 Longitude: -105.137589

FACILITY - API Number: 05-043- -00 Facility ID: 295254

Facility Name: RAINBOW Number: 23-20

Qtrqr: NESW Sec: 20 Twp: 19S Range: 69W Meridian: 6

Latitude: 38.379078 Longitude: -105.137589

CORRECTIVE ACTIONS:

1 ☒ CA# 165199

Corrective Action: Install sign to comply with Rule 605.d.

Date: 11/11/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator Comment: Upon notification by COGCC Inspectors Tom Beardslee and Randy Siver, operator immediately replaced faded placards with new placards and identified tank contents and tank volume by end of day on 10/11/22. See photo ATTACHMENT.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator all corrective actions appear to have been completed. See inspection Doc# 707900121.

2 ☒ CA# 165200

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 10/12/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator Comment: Operator was contacted by phone by COGCC Inspector Tom Beardslee to remedy mechanical issue with 24-hours. Operator responded immediately and tightened all valves, pipes and fittings and hammered wellhead tight. Operator confirmed wellhead leak repair with soapy water and saw no further indication (bubbles) of gas leaking around tubing. See photo ATTACHMENT.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos submitted by operator all corrective actions appear to have been completed. See inspection Doc# 707900121.

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator completed all CA's by end of inspection day on 10/11/22.
1) Replaced tank placards and identified tank contents and volume
2) Tightened and repaired leaking wellhead and confirmed all valves, pipes and fittings were tight
Also:
Resubmitted Form 42 Inspector Notice for MIRUSU and P&A on Rainbow, due to eqpt delay

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Liz Harkins

Signed: _____

Title: Engineer

Date: 10/13/2022 4:45:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403197253	FIR RESOLUTION SUBMITTED
403197293	Post CA completion photos

Total Attach: 2 Files