

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403209995

Date Received:  
10/27/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		FarmingtonRegulatoryTechs@hilcorp.com
Labowskie, Steve		steve.labowskie@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500658  
Inspection Date: 10/24/2022 FIR Submit Date: 10/24/2022 FIR Status:

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325466

Location Name: TIFFANY 2 Number: 3 County: LA PLATA  
Qtrqtr: SESE Sec: 2 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.042010 Longitude: -107.573250

FACILITY - API Number: 05-067-00 Facility ID: 419641

Facility Name: TIFFANY 2 Number: 3  
Qtrqtr: SESE Sec: 2 Twp: 32N Range: 7W Meridian: N  
Latitude: 37.042010 Longitude: -107.573250

CORRECTIVE ACTIONS:

1  CA# 165654

Corrective Action: Implement or modify BMPs for improved material handling and spill prevention per rule 1002.f.(2)B. Date: 11/04/2022

Response: CA COMPLETED Date of Completion: 10/26/2022

Operator Comment: Containment berm was built around the lube oil tank. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500658 has been satisfactorily completed, pending reinspection.

2  CA# 165655

Corrective Action: All unused equipment must be returned to use or stored off location per rule 606.

Date: 11/02/2022

Response: CA COMPLETED

Date of Completion: 10/26/2022

Operator Comment: All unused equipment has been removed from the site. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500658 has been satisfactorily completed, pending reinspection.

3  CA# 165656

Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.a(3)

Date: 10/27/2022

Response: CA COMPLETED

Date of Completion: 10/27/2022

Operator Comment: Installed valve on unused flow line and locked and tagged out. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500658 has been satisfactorily completed, pending reinspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: OperationsRegulatory Tech

Date: 10/27/2022 9:38:50 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403209995	FIR RESOLUTION SUBMITTED
403210005	Tiffany C 1_702500658_Resolved Photos

Total Attach: 2 Files