

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403215006

Date Received:
11/01/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 25250
Name of Operator: DUGAN PRODUCTION CORP
Address: P O BOX 420
City: FARMINGTON State: NM Zip: 87499-0420

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Wheeler, Cody</u>		<u>Cody.Wheeler@duganproduction.com</u>
<u>Alexander, John</u>		<u>johncalexander@duganproduction.com</u>
<u>Smaka, Kevin</u>		<u>kevin.smaka@duganproduction.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Feil, Tyra</u>		<u>tyrafeil@duganproduction.com</u>
<u>Heslop, Jason</u>		<u>Jason.Heslop@duganproduction.com</u>
<u>Foutz, Marty</u>		<u>marty.foutz@duganproduction.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500652
Inspection Date: 10/25/2022 FIR Submit Date: 10/24/2022 FIR Status: _____

Inspected Operator Information:

Company Name: DUGAN PRODUCTION CORP Company Number: 25250
Address: P O BOX 420
City: FARMINGTON State: NM Zip: 87499-0420

LOCATION - Location ID: 325498

Location Name: TIFFANY-N32N7W Number: 11NENW County: LA PLATA
Qtrqtr: NENW Sec: 11 Twp: 32N Range: 7W Meridian: N
Latitude: 37.035760 Longitude: -107.581670

FACILITY - API Number: 05-067-00 Facility ID: 214894

Facility Name: TIFFANY Number: 1
Qtrqtr: NENW Sec: 11 Twp: 32N Range: 7W Meridian: N
Latitude: 37.035760 Longitude: -107.581670

CORRECTIVE ACTIONS:

1 CA# 165651

Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.a(3) Date: 10/27/2022

Response: CA COMPLETED Date of Completion: 10/26/2022

Operator Comment: Locked and tagged flowline near separator & near wellhead. Note that these corrections were corrected on 10/26/22 & FIR submitted on 10/27/22.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500652 has been satisfactorily completed, pending reinspection.

2 CA# 165652

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C Date: 10/20/2022

Response: CA COMPLETED Date of Completion: 11/01/2022

Operator Comment: Access road rut repairs completed. Photos attached.

COGCC Decision: Approved pending re-inspection

COGCC Representative: CA from previous inspection Doc# 702500652 has been satisfactorily completed, pending reinspection.

OPERATOR COMMENT AND SUBMITTAL

Comment: Access road ruts fixed. Photos attached. Previous Field Inspection compliance issue for locked & tagged out on unused flowline near separator & unused flowline near wellhead completed 10/26/22, uploaded to COGCC 10/27/22.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyra M. Feil Signed: _____

Title: Engineering Assistant Date: 11/1/2022 11:58:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403215006	FIR RESOLUTION SUBMITTED
403215021	Access road corrections completed.

Total Attach: 2 Files