

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403183435

Date Received:
09/30/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 760 HORIZON DRIVE STE 400
City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Gas_UtahGasCorp</u>	<u>970-693-6021</u>	<u>inspections@utahgascorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204020
Inspection Date: 08/25/2022 FIR Submit Date: 08/29/2022 FIR Status: _____

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP Company Number: 10539
Address: 760 HORIZON DRIVE STE 400
City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 322317

Location Name: FEDERAL-CARBONERA-67S104W Number: 2NWNW County: _____
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 104W Meridian: 6
W
Latitude: 39.486663 Longitude: -108.963042

FACILITY - API Number: 05-045-00 Facility ID: 322317

Facility Name: FEDERAL-CARBONERA-67S104W Number: 2NWNW
Qtrqtr: NWN Sec: 2 Twp: 7S Range: 104W Meridian: 6
W
Latitude: 39.486663 Longitude: -108.963042

CORRECTIVE ACTIONS:

1 CA# 164178

Corrective Action: Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.

Date: 09/13/2022

Response: CA COMPLETED Date of Completion: 09/30/2022

Operator Comment: Please note this CA has NOT been corrected yet. I was unable to save this without choosing an option. UGC has been trying to get to this location to fix the CA- Comply with 1002.f; maintain access road; implement and maintain BMPs to stabilize access road, manage runoff and minimize further degradation. The weather has prevented us from getting there but hope to be able to address the week of 10/3/2022. We will submit a follow-up FIRR as soon as issue is corrected.

COGCC Decision: **Not Approved**

COGCC Representative: Though Staff appreciates and acknowledges UGC's intent to provide the COGCC with an update, an Operator response of "CA Complete" within a Resolution is a notification to the State that the corrective action has been addressed pursuant to Rule 210.b; therefore Staff is unable to accept this Resolution.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please note this CA has NOT been corrected yet. I was unable to save this without choosing an option. UGC has been trying to get to this location to fix the CA- Comply with 1002.f; maintain access road; implement and maintain BMPs to stabilize access road, manage runoff and minimize further degradation. The weather has prevented us from getting there but hope to be able to address the week of 10/3/2022. We will submit a follow-up FIRR as soon as issue is corrected.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: April Mestas Signed: _____

Title: Regulatory Manager Date: 9/30/2022 11:11:43 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403183435	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files