

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403200476

Date Received:
10/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.Inspections

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203985

Inspection Date: 08/15/2022

FIR Submit Date: 08/19/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334776

Location Name: FEDERAL-67S95W Number: 12SESW County: _____

Qtrqr: SESW Sec: 12 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.446006 Longitude: -107.947547

FACILITY - API Number: 05-045- -00 Facility ID: 334776

Facility Name: FEDERAL-67S95W Number: 12SESW

Qtrqr: SESW Sec: 12 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.446006 Longitude: -107.947547

CORRECTIVE ACTIONS:

2 ☒ CA# 163985

Corrective Action: Comply with 1002.f and implement stabilization and tracking BMPs; regrading efforts alone will be insufficient.

Date: 08/26/2022

Response: CA COMPLETED

Date of Completion: 08/22/2022

Operator Comment: Location was bladed and 8 loads of gravel were delivered and spread across problem spots on the pad. Corrective action #163985 is complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.
-----------------------	--

OPERATOR COMMENT AND SUBMITTAL

Comment:	Location was bladed and 8 loads of gravel were delivered and spread across soft spots on the pad. Corrective action #163985 is complete.
----------	--

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 10/18/2022 10:54:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

403200476	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files