

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403234818

Date Received:
11/18/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>General</u>		<u>sjninspections@ikavenergy.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500546

Inspection Date: 10/04/2022

FIR Submit Date: 10/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325490

Location Name: PINE RIVER UNIT-M34N6W Number: 29NWSW County: LA PLATA

Qtrqr: NWS Sec: 29 Twp: 34N Range: 6W Meridian: M
W

Latitude: 37.159252 Longitude: -107.528121

FACILITY - API Number: 05-067-00 Facility ID: 214879

Facility Name: PINE RIVER Number: 2-29 #2

Qtrqr: NWS Sec: 29 Twp: 34N Range: 6W Meridian: M
W

Latitude: 37.159252 Longitude: -107.528121

CORRECTIVE ACTIONS:

1 CA# 165022

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 11/04/2022

Response: CA COMPLETED

Date of Completion: 11/02/2022

Operator Comment: Weeds controlled and berm repaired.

COGCC Decision: _____

COGCC
Representative:

2 CA# 165023

Corrective Action:

Ensure within 25' of wellhead, tanks, and separators are free of combustible material per rule 610.k

Date: 10/13/2022

Response: CA COMPLETED

Date of Completion: 10/31/2022

Operator
Comment:

Weeds removed around equipment with mechanical removal.

COGCC Decision: _____

COGCC
Representative:

3 CA# 165024

Corrective Action:

Install or repair/modify required BMPs per Rule 1002.f.(2)C, including ditches in order to minimize and control erosion and sediment migration.

Date: 11/04/2022

Response: CA COMPLETED

Date of Completion: 11/02/2022

Operator
Comment:

Erosion channels repaired along access road.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: _____

Title: Permitting Specialist I

Date: 11/18/2022 3:51:27 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403234822	Pine River 2-29 2, CA Complete Photos
403234823	Pine River 2-29 2, Weed CA Complete Photos

Total Attach: 2 Files