

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403234243

Date Received:
11/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Laramie

970-248-0497

cogccnotifications@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204047

Inspection Date: 08/30/2022

FIR Submit Date: 09/02/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 324373

Location Name: Shell Number: 797-14-01D County: _____

Qtrqr: NWN Sec: 14 Twp: 7S Range: 97W Meridian: 6

Latitude: 39.451974 Longitude: -108.193122

FACILITY - API Number: 05-045-00 Facility ID: 324373

Facility Name: Shell Number: 797-14-01D

Qtrqr: NWN Sec: 14 Twp: 7S Range: 97W Meridian: 6

Latitude: 39.451974 Longitude: -108.193122

CORRECTIVE ACTIONS:

2 ☒ CA# 164319

Corrective Action: Comply with 1003 Rules and conduct additional revegetation activities; ensure BMPs are installed to stabilize the seeded soils and continue to monitor/manage interim areas to ensure site progresses towards 1003 standards.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 11/15/2022

Operator
Comment:

We have reseeded this area

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed.

Based on the photos provided, it is unclear if the work conducted will be adequate to ensure location progresses towards 1003 standards, additionally BMPs to ensure seed is stabilized do not appear to have been implemented per the CA.

A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 11/18/2022 11:04:56 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403234243	FIR RESOLUTION SUBMITTED
403234247	Reseed Photos

Total Attach: 2 Files