

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403244608

Date Received:
11/30/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ferrin, Jeremy

jeremy.ferrin@state.co.us

daniel.gray@usda.gov

heather.lang@oxbow.com

Kosola, Jason

jason.kosola@state.co.us

dnr_cogccenforcement@state.co.us

—

Toews, Wesley

wtoews@blm.gov

geops@oxbow.com

Fischer, Alex

alex.fischer@state.co.us

tyson.johnston@oxbow.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204280

Inspection Date: 11/01/2022

FIR Submit Date: 11/02/2022

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 453805

Location Name: Trail Gulch Unit 1090 Number: 30 County: _____

Qtrqr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

FACILITY - API Number: 05-051-00 Facility ID: 453805

Facility Name: Trail Gulch Unit 1090 Number: 30

Qtrqr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

CORRECTIVE ACTIONS:**1** CA# 165866Corrective Action: Install or repair wildlife protection equipment.Date: 11/07/2022Response: CA COMPLETEDDate of Completion: 11/04/2022Operator Comment: Chicken Wire installed around tank containment for wildlife protection as shown in FIRR Doc. #403227353.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 165867Corrective Action: Comply with Rule 1002.f and install BMPs to minimize erosion/degradation/sediment transport, and to protect/stabilize the cut slopes of the Location.Date: 06/18/2021Response: CA COMPLETEDDate of Completion: 11/21/2022Operator Comment: In reference to FIRR Doc. #403227353, the hydro mulch and seeding was completed between 11/17 and 11/21 on all cut slopes and the top soil stockpile. All slopes are currently stabilized as required by the rule.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 165868Corrective Action: Comply with Rule 1002.f and Rule 1002.c.Date: 05/21/2021Response: CA COMPLETEDDate of Completion: 11/21/2022Operator Comment: In reference to FIRR Doc. #403227353, the hydro mulch and seeding was completed between 11/17 and 11/21 on all cut slopes and the top soil stockpile. All slopes are currently stabilized as required by the rule. (see photos)

COGCC Decision: _____

COGCC Representative: _____

4 CA# 165869Corrective Action: Contact West Environmental Supervisor A. Fischer (alex.fischer@state.co.us) regarding possible closure and sampling requirements associated with the Minion tanks.Date: 11/04/2022Response: CA COMPLETEDDate of Completion: 11/18/2022Operator Comment: In conversation with Mr. Fischer, Gunnison Energy is voluntarily testing where the minion tanks were placed, despite such not being required by the Waste Management Plan approved for their use. Because there was NOT a COA for this action, and due to the fact that this is an engineering concern, this should not be a CA on this inspection, therefore should not be denied as resolved as it should not have been included. Gunnison currently has WSP drafting a plan and form 27 for the voluntary minion location soil samples.

COGCC Decision: _____

COGCC Representative: _____

5 CA# 165870

Corrective Action: _____

Date: 11/01/2022

Comply with 1002.c and 1002.f; immediately remove soil stockpiles from the perimeter stormwater ditch and properly store. Implement BMPs in accordance with good engineering practices at all stockpiled soils to minimize erosion, degradation and sediment transport. Contact West Environmental Supervisor A. Fischer (alex.fischer@state.co.us) regarding possible additional Environmental requirements.

Response: CA COMPLETED

Date of Completion: 11/18/2022

Operator Comment: All soil piles were hauled away to approved waste facilities and GE will address any other concerns through the closeout process for the open form 27 for those samples. Mr. Fischer included on the FIRR contact.

COGCC Decision:

COGCC Representative:

6 CA# 165871

Corrective Action: Comply with 1002.f; implement BMPs at the excavated sample pits within ditch along east end of the Location, in order to prevent potential impacts to stormwater runoff.

Date: 11/01/2022

Response: CA COMPLETED

Date of Completion: 11/18/2022

Operator Comment: All soil piles were hauled away to approved waste facilities and GE will address any other concerns through the closeout process for the open form 27 for those samples. Mr. Fischer included on the FIRR contact.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed:

Title: Vice President

Date: 11/30/2022 1:56:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403244814	Seeding and Mulch 1
403244818	Seeding and Mulch 2
403244823	Seeding and Mulch 3
403244828	Seeding and Mulch 4
403244832	Seeding and Mulch 5
403244835	Seeding and Mulch 6

Total Attach: 6 Files