

FORM
6Rev
11/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

403154195

Date Received:

09/01/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: Candice Barber

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Phone: (307) 2334513

Address: P O BOX 173779

Fax:

City: DENVER State: CO Zip: 80217-

Email: candice_barber@oxy.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

Type of Well Abandonment Report:



Notice of Intent to Abandon



Subsequent Report of Abandonment

API Number 05-123-19540-00

Well Name: HSR-BEDDO

Well Number: 6-25

Location: QtrQtr: NWNE Section: 25 Township: 3N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.201555

Longitude: -104.836316

GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: PDOP Date of Measurement: 08/15/2022

Reason for Abandonment:



Dry



Production Sub-economic



Mechanical Problems

☐ Other

Casing to be pulled:



Yes



No

Estimated Depth:

Fish in Hole:



Yes



No

If yes, explain details below

Wellbore has Uncemented Casing leaks:



Yes



No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7788	7798	04/05/2022	B PLUG CEMENT TOP	7500
NIOBRARA	7525	7587	04/05/2022	B PLUG CEMENT TOP	7500

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	805	605	805	0	VISU
1ST	7+7/8	4+1/2	I-80	11.6	0	7961	125	7961	7088	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7500 with 2 sacks cmt on top. CIBP #2: Depth 260 with 85 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 85 sks cmt from 260 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 6000 ft. with 200 sacks. Leave at least 100 ft. in casing 5360 CICR Depth
Perforate and squeeze at 4737 ft. with 220 sacks. Leave at least 100 ft. in casing 4148 CICR Depth
Perforate and squeeze at 3550 ft. with 220 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 120 sacks half in. half out surface casing from 905 ft. to 608 ft. Plug Tagged: ☒

Set 5 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 905 ft. of 4+1/2 inch casing

Surface Plug Setting Date: 04/14/2022 Cut and Cap Date: 08/12/2022 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 120

*Wireline Contractor: CUTTERS

*Cementing Contractor: SCHLUMBERGER

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

CONTINUED PLUGGING PROCEDURE:

PERF AT 2250' WITH 220 SACKS OF CEMENT, TAGGED TOC IN CASING AT 1231'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Candice Barber

Title: REGULATORY ANALYST Date: 9/1/2022 Email: DJPOSTDRILL@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 12/5/2022

CONDITIONS OF APPROVAL, IF ANY:

COA Type Description

0 COA	
-------	--

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
403154195	FORM 6 SUBSEQUENT SUBMITTED
403154221	OPERATIONS SUMMARY
403154222	CEMENT JOB SUMMARY
403154223	WELLBORE DIAGRAM
403154225	WIRELINE JOB SUMMARY
403154232	OTHER

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Reported as-drilled well location. Reviewed attachments. Pass.	11/02/2022

Total: 1 comment(s)