

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403027487

Date Received:  
04/26/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Arthur, Denise</u>		<u>regulatory@foundationenergy.com</u>
<u>Pesicka, Conor</u>		<u>denise.arthur@state.co.us</u>
<u>Cowan, Peter</u>		<u>conor.pesicka@state.co.us</u>
<u>Koehler, Vernon E.</u>	<u>970-834-9272</u>	<u>picowan@blm.gov</u>
		<u>vkoehler@fs.fed.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 691200437  
Inspection Date: 09/07/2018 FIR Submit Date: 09/09/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 331181

Location Name: FEDERAL OSPREY-68N60W Number: 35NENW County: \_\_\_\_\_  
Qtrqtr: NENW Sec: 35 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.622480 Longitude: -104.061270

FACILITY - API Number: 05-123-00 Facility ID: 331181

Facility Name: FEDERAL OSPREY-68N60W Number: 35NENW  
Qtrqtr: NENW Sec: 35 Twp: 8N Range: 60W Meridian: 6  
Latitude: 40.622480 Longitude: -104.061270

CORRECTIVE ACTIONS:

1  CA# 118534

Corrective Action: Comply w/ Rule 605.d.  
Previous CA date remains applicable.

Date: 11/03/2016

Response: CA COMPLETED

Date of Completion: 06/14/2019

Operator Comment: Follow up inspection doc #696101035 noted that this wellsite is not located within designated setback area, and therefore, noise abatement is not required. Inspection date is entered here as the date of completion.

COGCC Decision: Approved

COGCC Representative: Follow up FIR inspection doc #696101035 dated 06/14/2019 notes that this wellsite is not located within designated setback area, and therefore, noise abatement is not required.

**2**  CA# 118535

Corrective Action: Comply with Rule 603.f . Date: 09/20/2018

Response: CA COMPLETED Date of Completion: 06/14/2019

Operator Comment: Follow up inspection doc #696101035 stated that this corrective action was addressed; the weeds inside of the pit area were mitigated. Inspection date is entered as date of completion.

COGCC Decision: Approved

COGCC Representative: Follow up FIR inspection doc #696101035 dated 06/14/2019 notes corrective action was addressed.

**3**  CA# 118536

Corrective Action: Comply with Rule 605.d. Date: 10/10/2018

Response: CA COMPLETED Date of Completion: 06/14/2019

Operator Comment: Follow up inspection doc #696101035 states that this corrective action was addressed; bradenhead was plumbed to surface.

COGCC Decision: Approved

COGCC Representative: Follow up FIR inspection doc #696101035 dated 06/14/2019 notes corrective action was addressed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action items were addressed. Please reference FIR Doc #696101035.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton liams Signed: \_\_\_\_\_

Title: HSE/Regulatory Technician Date: 4/26/2022 9:30:09 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403027487	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files