


# Buffalo Gold 34-4

Pit Reconciliation

#112906

# Internal Database


- No indication of onsite pit since 2009 on internal inspections
- Internal database indicates no pit constructed on location



1999 Google Earth photo

# Permit (#657013)

- The following message is found on page two of the permit from the scout card
- No form 27 is on the scout card, never filed
- Does form 27 need to be filed, or can pit be administratively closed?



COGCC needs  
Form 27  
Does not need  
Approval  
Tank Set!

# Conclusion

- Pit needs to be administratively closed
- No 909J sampling required. Removed from sampling schedule.