

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2022

Submitted Date:

12/19/2022

Document Number:

695107125

FIELD INSPECTION FORM

Loc ID 322279 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 17210
Name of Operator: CINNAMON CREEK OIL & GAS INC
Address: P O BOX 544
City: WALSH State: CO Zip: 81090

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Mills, Hellen		heleningle1221@yahoo.com	All Inspections
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210102	WELL	PR	07/01/2021	OW	043-40039	COWPERTHWAITTE 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	PHOTO 5: NFPA placards faded and peeling off ON WEST TANK.		
Corrective Action:	Install sign to comply with Rule 605.g. THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION REQUIRED.	Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Bradenhead	# 1			
Comment:	PHOTO 6: Bradenhead inaccessible or not visible.			
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION REQUIRED.			Date:
Type: Ancillary equipment	# 1			
Comment:	ELECTRIC POWER POLE			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		38.301576,-105.104108
Comment:	PHOTO 7: Risers on tanks are BULL PLUGGED. Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION REQUIRED.				
Corrective Action:	Tanks will function as sealed and ventless with gas released only through a vapor control system or properly sized pressure relief valve. THIS IS SECOND NOTICE FOR THIS CORRECTIVE ACTION, IMMEDIATE ACTION REQUIRED.				Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) BBL 210	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 210102 Type: WELL API Number: 043-40039 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP DOC #707900071, NOT ALL CA'S HAVE BEEN ADDRESSED IMMEDIATE ACTION IS REQUIRED.	beardslt	12/19/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695107126	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5951626