

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/23/2022

Submitted Date:

12/27/2022

Document Number:

707800079**FIELD INSPECTION FORM**
 Loc ID 335304 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259709	WELL	PR	03/21/2002	GW	045-07765	CLOUGH RMV 143-18	PR
272639	WELL	PR	03/08/2005	GW	045-10108	CLOUGH RWF 434-18	PR
272641	WELL	PR	11/01/2017	GW	045-10107	CLOUGH RWF 533-18	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 12/23/2022, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 533-18, at Location # 335304 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Well signage fading

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	Snow covered		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head signage is becoming illegible		
Corrective Action:	Provide proper signage	Date:	02/07/2023

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
-----------------	--	--	--

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 259709 Type: WELL API Number: 045-07765 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 272639 Type: WELL API Number: 045-10108 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 272641 Type: WELL API Number: 045-10107 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707800085	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5960805