

FORM 6 Rev 11/20	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		 		DE	ET	OE	ES
					Replug By Other Operator			

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: <u>10661</u>	Contact Name: <u>Adam Conry</u>
Name of Operator: <u>CIVITAS NORTH LLC</u>	Phone: <u>(720) 225-6663</u>
Address: <u>555 17TH STREET #3700</u>	Fax: _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>	Email: <u>aconry@civiresources.com</u>

For "Intent" 24 hour notice required, Name: _____ Tel: _____

COGCC contact: Email: _____

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number <u>05-123-08763-00</u>	Well Number: <u>1</u>
Well Name: <u>PACKARD</u>	
Location: QtrQtr: <u>NENE</u> Section: <u>11</u> Township: <u>5N</u> Range: <u>61W</u> Meridian: <u>6</u>	
County: <u>WELD</u> Federal, Indian or State Lease Number: _____	
Field Name: <u>WILDCAT</u> Field Number: <u>99999</u>	

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.421397 Longitude: -104.168363

GPS Data: GPS Quality Value: _____ Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 10/15/1976

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems

☐ Other _____

Casing to be pulled: ☐ Yes ☐ No Estimated Depth: _____

Fish in Hole: ☐ Yes ☐ No If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	212	225	212	0	VISU
OPEN HOLE	7+7/8				212	6775				

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set	75	sks cmt from	6700	ft. to	6550	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	75	sks cmt from	5997	ft. to	5847	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input type="checkbox"/>
Set	90	sks cmt from	2200	ft. to	1895	ft.	Plug Type:	OPEN HOLE	Plug Tagged:	<input checked="" type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>
Set		sks cmt from		ft. to		ft.	Plug Type:		Plug Tagged:	<input type="checkbox"/>

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 1000 sacks half in. half out surface casing from 800 ft. to 0 ft. Plug Tagged: ☐

Set 30 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 11/29/2022 Cut and Cap Date: 12/09/2022 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 10

*Wireline Contractor: _____

*Cementing Contractor: Swabbco

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☒ No

Technical Detail/Comments:

1). Form 42 was submitted prior to plugging operations, Form 42 Doc # 403241468. Form 42 was submitted prior to MIRU for plugging operations, Form 42 Doc #403241458

2). Plugs were placed as stated in the plugging procedure on the form 6 NOI

3). The Wellbore was static prior to placing plugs. all plugs have at least 100' of cement.

4). Plug was cemented to surface and topped off w/ 30 sx at surface (Total sx 1030).800' to surface

No fluids or gas migration was present prior to cement plug to surface being set.

5).This form 6-SRA addresses all COA's from the Form 6-NOIA.

6).After placing plug at from 5997-5847' well was static.

7) plugging procedure followed the changes.

Attached to this form:

a. Wireline and cement tickets are attached to this form.

b. Operations summary is attached to this form for reference.

c. Final P&A WBD is attached to this form.

Venting health and safety precautions were taken to avoid nuisance and or hazards to the public.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Ashley Noonan

Title: Sr. Regulatory Analyst

Date: _____

Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

0 COA	

Attachment List

Att Doc Num

Name

403276807	CEMENT JOB SUMMARY
403276808	OPERATIONS SUMMARY
403280023	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)