



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator
 Document Number:
 403269722
 Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10661 Contact Name: Adam Conry
 Name of Operator: CIVITAS NORTH LLC Phone: (720) 225-6663
 Address: 555 17TH STREET #3700 Fax: _____
 City: DENVER State: CO Zip: 80202 Email: aconry@civiresources.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 Email: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-05173-00
 Well Name: HUYLER Well Number: 1
 Location: QtrQtr: NESE Section: 23 Township: 5N Range: 61W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WILDCAT Field Number: 99999

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.384927 Longitude: -104.168743
 GPS Data: GPS Quality Value: _____ Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 07/23/1956
 Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J-55	24	0	200	200	200	0	VISU
1ST	7+7/8	5+1/2	J-55	15.50	0	6632	150	6632	5990	CALC

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 75 sks cmt from 6554 ft. to 6300 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 125 sks cmt from 2300 ft. to 1898 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set 420 sacks half in. half out surface casing from 800 ft. to 0 ft. Plug Tagged:
Set 60 sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 6
Surface Plug Setting Date: 12/03/2022 Cut and Cap Date: 12/09/2022

*Wireline Contractor: _____ *Cementing Contractor: Swabbco

Type of Cement and Additives Used: Class G

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

- 1). Form 42 was submitted prior to plugging operations, Form 42 Doc #403239471. Form 42 was submitted prior to MIRU for plugging operations, Form 42 Doc #403239470
- 2). Plugs were placed as stated in the Plugging Procedure section of the approved NOIA.
- 3). At least 100' of cement was left in the wellbore for each plug.
- 4). No fluids or gas migration was present prior to cement plug to surface being set. The plug was cemented to surface with 480 sacks of cement from 800'. Plug was cemented to surface and topped off w/ 30sx at surface (Total sx 510).
- 5). This form 6-SRA addresses all COA's from the Form 6-NOIA.
- 6). After placing plug at 5665', operator waited a sufficient amount of time to confirm static conditions. There was no pressure or fluid migration.
- 7) Plugging procedure has been modified as follows,
Plug #1 - 6554', 75 sx cement casing plug
Plug #2 - 2300', 125 sx
Plug #3 - 800-0', 450 sx cement open hole plug intended to circulate to the surface and remain there.

Attached to this form:

- a. Cement tickets are attached to this form.
- b. Operations summary is attached to this form for reference.
- c. Final P&A WBD is attached to this form.

Venting health and safety precautions were taken to avoid nuisance and or hazards to the public.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Ashley Noonan
Title: Sr. Regulatory Analyst Date: _____ Email: regulatory@civiresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type Description

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

Att Doc Num Name

403282339	CEMENT JOB SUMMARY
403282441	WELLBORE DIAGRAM
403282448	OTHER
403282453	OPERATIONS SUMMARY

Total Attach: 4 Files

General Comments

User Group Comment

Comment Date

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)