

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2023

Submitted Date:

01/09/2023

Document Number:

697006992

FIELD INSPECTION FORMLoc ID 432476 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10642

Name of Operator: EWS 3 DJ BASIN LLC

Address: 2015 CLUBHOUSE DR SUITE 201

City: GREELEY State: CO Zip: 80634

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goddard, Jim		jgoddard@expedition-water.com	
Kraich, Adam		adam.kraich@state.co.us	
Gage, Dave	(970) 590-6463	Dgage@expedition-water.com	Facility Manager EWS #3
Morgan, John		john.morgan@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432474	WELL	IJ	08/01/2017	DSPW	123-37120	EWS 3	AC

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 432474 Type: WELL API Number: 123-37120 Status: IJ Insp. Status: AC**Underground Injection Control**UIC Violation: Operational Violation Maximum Injection Pressure: _____UIC RoutineInj./Tube: Pressure or inches of Hg 2125 psig Previous Test Pressure _____ MPP _____

(e.g. 30 psig or -30" Hg)

Inj Zone: DJINJTC: Pressure or inches of Hg 2000 psig Previous Test Pressure _____ Last MIT: 01/18/2019Brhd: Pressure or inches of Hg 0 psig Previous Test Pressure _____ AnnMTReq: _____Comment: All injection wells which fail MIT or which are determined to lack mechanical integrity shall be shut in.Corrective Action: Immediately shut in well and disconnect flowline or disable/LOTO injection pump Date: 01/09/2023Method of Injection: PUMP FEED

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 12/05/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 1/9/2023 at approximately 10:20 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Expedition Water Services EWS #3 well API #123-37120 in Weld County, Colorado.</p> <p>While there, I observed that the well lacked mechanical integrity. The operator immediately ceased injection operations. During this inspection the following possible compliance issues were observed: Rule 417.f. with a corrective action date of 1/9/2023.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	01/09/2023

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697006993	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5975062