

state

F  
(1)

00263318

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Fee

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Pierce

8. FARM OR LEASE NAME

Gertrude L. King

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Pierce-Lyons

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 22, T8N R66W  
6th PM

12. COUNTY OR PARISH

Weld

13. STATE

Colorado

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL  
WELL
☐
GAS  
WELL
☐

OTHER

Water Injection

2. NAME OF OPERATOR

Chevron Oil Company - Western Division

3. ADDRESS OF OPERATOR

P. O. Box 599, Denver, Colorado 80201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below.)  
At surface1957' S of N and 1974' E of W (SE $\frac{1}{4}$ , NW $\frac{1}{4}$ )

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Ground 5068

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☒  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

It is planned to P & A the well as follows:

1. Set 100 sxs. cement plug 6375-5472. Tag top of cement.
2. Set 50 sxs. cement plug 1500-1060.
3. Cut off casing below plow depth.
4. Mix 10 sxs. cement plug in top of casing.

DP	<input checked="" type="checkbox"/>
FJP	<input checked="" type="checkbox"/>
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JD	<input checked="" type="checkbox"/>

Oral approval of above procedure was obtained from Mr. E. R. Haymaker with the U.S.G.S. and Mr. Morrell with Colorado State on June 12, 1970.



18. I hereby certify that the foregoing is true and correct

SIGNED

Original Signed by  
P. F. HAMILTON

TITLE

P. F. Hamilton  
Lead Drilling Engineer

DATE

6/12/70

(This space for Federal, or State, or Local use)

APPROVED BY

E. R. Haymaker

TITLE

DATE

JUN 18 1970

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side