



99999999

OIL AND GAS CONSERVATION COMMISSION
INSPECTION REPORT

- ☒ NOTICE OF UNSATISFACTORY INSPECTION
☐ NOTICE OF SATISFACTORY INSPECTION


1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 107 - 5089		LEASE NAME: State #5	
LOCATION: SENW, 18, 6N, 86W		OPERATOR: BG Cannon	
DATE: 8-22-96		INSPECTOR: Adkins	
Insp. Type: ID	Insp. Status: TA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F Viol: Y <input checked="" type="radio"/> N NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	ok	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	to common pit	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	none	
Tank Battery Equipment (Rule 603.b.3, 604)	1-RPU (no prime mover)	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	n/a	
General Housekeeping (Rule 603)	ok	
Spills (Oil/Water) (Rule 907)	around wellhead	
Bradenhead (Rule 207.b)	n/a	
Drilling Well/Workover (Rule 317)	n/a	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	n/a	
Miscellaneous	 00212850	

CORRECTIVE ACTION REQUIRED: Perform MIT or Return to Production on
PTA by 8-1-97

Date Corrective Action Required By: 8-1-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.