



OGCC FORM 4
Rev. 8/89

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

☒ OIL WELL ☐ GAS WELL ☐ COALBED METHANE ☐ INJECTION WELL ☐ OTHER

1 NAME OF OPERATOR

Western Operating Company

2 ADDRESS OF OPERATOR

518 - 17th Street, Suite 1680

CITY

STATE

ZIP CODE

Denver

CO

80202

4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements)

See also space 17 below

At surface

1980' FSL & 660' FEL of Section 8

At proposed prod. zone

Same

12 COUNTY

Kiowa

5 FEDERAL INDIAN OR STATE LEASE NO.

6 PERMIT NO.

71-266

7 API NO.

05-061-6105

8 WELL NAME

King Pyles

9 WELL NUMBER

No. 3

10 FIELD OR WILDCAT

Brandon

11 QTR QTR SEC. T.R. AND MERIDIAN

NESE Section 8

T19S-R45W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
- ☐ MULTIPLE COMPLETION
- ☐ COMMINGLE ZONES
- ☐ FRACTURE TREAT
- ☐ REPAIR WELL
- ☐ OTHER

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ☐ ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- ☐ REPAIRED WELL
- ☐ OTHER

*Use Form 3 - Well Completion or Recompletion Report and Log for subsequent reports of Multiple/Commingle Completions and Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS)
- ☐ PRODUCTION RESUMED (DATE _____)
- ☐ LOCATION CHANGE (SUBMIT NEW PLAT)
- ☐ WELL NAME CHANGE
- ☐ OTHER

14 DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15 DATE OF WORK Third (3rd) Quarter, 1996

1. TIH w/2-7/8" tbg. Tag sand plug to check depth. Spot 10 sx cement plug @ 4570'± or tag w/wireline & dump bail 10 sx plug.
2. Spot 40 sx plug @ 3080'. Let cement set up. Fill csg w/water.
3. Perf csg w/4 holes @ 1300'. Set cement retainer @ 1250'. Squeeze 113 sx cement through holes @ 1300'. Spot 2 sx on top of retainer.
4. Perf 4 holes @ 190'. Squeeze 25 sx through holes @ 190' & leave 25 sx plug in csg. (50 sx total). 210'
5. Set 10 sx plug @ surface. Put 5 sx in 8-5/8" & 5 sx in 5-1/2". Cut off 8-5/8" & 5-1/2" 4'+below ground level. Cap w/1/4" or thicker plate that reads - King Pyles #3 NESE Sec. 8 T19S-R45W
6. Reclaim location.

16. I hereby certify that the foregoing is true and correct

SIGNED

TELEPHONE NO. (303) 893-2438

NAME (PRINT) Steven D. James

TITLE Vice President

DATE March 29, 1996

(This space for Federal or State office use)

APPROVED

TITLE

DATE

4/3/96

CONDITIONS OF APPROVAL, IF ANY: