



OGCC FORM 4
Rev. 8/89

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES



SUBMIT ORIGINAL AND 1 COPY

| FOR OFFICE USE ONLY | | | |
|---------------------|----|----|----|
| ET | FE | UC | SE |

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1

OIL WELL GAS WELL COALBED METHANE INJECTION WELL OTHER

2 NAME OF OPERATOR

WESTERN OPERATING COMPANY

3 ADDRESS OF OPERATOR

518 -17TH ST., SUITE 1680

| | | |
|--------|-------|----------|
| CITY | STATE | ZIP CODE |
| DENVER | CO | 80202 |

4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface 1980' FNL & 1980' FEL OF SEC. 8

At proposed prod zone

SAME

12 COUNTY

KIOWA

5 FEDERAL INDIAN OR STATE LEASE NO

6 PERMIT NO
71-318

7 API NO
05-061-06107

8 WELL NAME
DAWSON

9 WELL NUMBER
NO. 6

10 FIELD OR WILDCAT
BRANDON

11 QTR. QTR. SEC., T.R. AND MERIDIAN
SW/4 NE/4 SEC. 8
T19S-R45W ✓

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- PLUG AND ABANDON
- MULTIPLE COMPLETION
- COMMINGLE ZONES
- FRACTURE TREAT
- REPAIR WELL
- OTHER _____

VP

13B. SUBSEQUENT REPORT OF:

- FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- REPAIRED WELL
- OTHER _____

**Use Form 3 - Well Completion or Recompletion Report and Log for subsequent report of Multiple/Commungled Completions and Recompletions*

13C. NOTIFICATION OF:

- SHUT-IN TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS)
- PRODUCTION RESUMED (DATE _____)
- LOCATION CHANGE (SUBMIT NEW PLAT)
- WELL NAME CHANGE
- OTHER _____

14. DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent)

15. DATE OF WORK _____

1. Set cmt retainer on top of fish (parted 2-7/8" tbg) @ 2556'±. Mix & pump 200 sxs cmt. Spot 2 sxs on top of cmt retainer.
2. Load csg w/wtr. Spot 10 sx plug @ 1400'±. Let cmt set up.
3. Perf 4 holes in 5-1/2" csg @ 1300' ±. Set cmt retainer @ 1250'. Squeeze 115 sxs cmt through retainer. Spot 2 sxs cmt on top of retainer.
4. Perf 4 holes in 5-1/2" csg @ 194'. Pmp 50 sx plug, 25 sx out 5-1/2" & leave 25 sxs inside 5-1/2" csg.
5. Set 10 sx plug @ sfc. Put 5 sxs in 8-5/8" & 5 sxs in 5-1/2" csg. Cut 8-5/8" & 5-1/2" csg 4' + below ground level. Weld on 3/8" thick cap that reads: Dawson #6, SW NE Sec. 8-T19S-R45W.
6. Reclaim location.

16. I hereby certify that the foregoing is true and correct

SIGNED _____

TELEPHONE NO. 303/893-2438

NAME (PRINT) STEVEN D. JAMES

TITLE VICE PRESIDENT

DATE _____

(This space for Federal or State office use)

APPROVED _____

CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE

8/26/96
PROVIDE 24 HR NOTICE OF MIRD TO BOB VANSTICKLE