



STATE OF COLORADO  
OIL AND GAS CONSERVATION COMMISSION  
Department of Natural Resources  
Suite 380, Logan Tower Building  
1580 Logan Street  
Denver, Colorado 80203

1 nexco

Lease #6 DAWSON  
Field BRANDON  
County KIOWA  
Location S.W. 8-19S-45W

Gentlemen:

An inspection was made of the lease(s) shown above. The following conditions were observed to exist at the time of the inspection:

- ☐ Oil accumulation on the water in the retaining pit.
- ☐ Skim pit in need of repairs.
- ☐ Skim pit or tank should be constructed.
- ☐ No. I.D. number on tank.

Remarks: X WELL APPEARS TO BE TEMPORARILY ABANDONED - REPORT

STATUS ~~AND~~ OF WELL

The above condition(s) should be corrected immediately. Any surface accumulation of oil in the retaining pits must be cleaned off within ten (10) days after receipt of this notice (Rule 328), and a report submitted to this office within thirty (30) days after the work was accomplished, advising us of the date and manner in which the correction was made. Any person who fails to comply with this request is in violation of this Commission's Rules and Regulations and is subject to the penalties as provided for under 34-6-121 of the Oil and Gas Conservation Act.

William R. Smith

William R. Smith, Director