



COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

C

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- <i>03M243</i> - <i>06185</i>		LEASE NAME: <i>Montgomery</i> <i>1-21</i>	
LOCATION: <i>SESE-521-1N-69W</i>		OPERATOR: <i>Greys Oil</i>	
DATE: <i>2-18-96</i>		INSPECTOR: <i>Paul Ka</i>	
Insp. Type: <i>CO</i>	Insp. Status: <i>PHA</i>	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: <i>P</i> F Viol.: Y <input type="radio"/> N <input checked="" type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: *Ed Dimattio requested inspection, because of land owner concerns of spill contamination & pulling tubing when arrived on*
Date Corrective Action Required By: *location* Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.