

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/06/2023

Submitted Date:

02/06/2023

Document Number:

702200033

**FIELD INSPECTION FORM**

Loc ID: 321441 Inspector Name: HICKEY, MIKE On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 79905  
Name of Operator: SMITH OIL PROPERTIES INC  
Address: PO BOX 219  
City: BYERS State: CO Zip: 80103

**Findings:**

2 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hickey, Mike		michael.hickey@state.co.us	

**General Comment:**

OWP Inspection in response to Boulder County email.

**COGCC Comments**

Comment	User	Date
Master valve showed signs of dried liquid residue. No gas leaks were detected either audibly or with soapy water. No liquids or sheen were observed on the ground. The double kimray valves are unusual.	hickeymi	02/06/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702200034	Futhy-Karma 2-26 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014099">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014099</a>
702200035	Futhy-Karma 2-26 plunger wellhead configuration	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014100">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014100</a>
702200036	Futhy-Karma 2-26 oil residue on equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014101">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6014101</a>