

**TEP Rocky Mountain LLC
Bosely SG 41-27
Location #334600**



Location entrance

Location entrance

TEP Rocky Mountain LLC

Bosely SG 41-27

Location #334600



Tank battery sign



Open end tank valves

**TEP Rocky Mountain LLC
Bosely SG 41-27
Location #334600**



Random debris at separator

Random debris at separator

**TEP Rocky Mountain LLC
Bosely SG 41-27
Location #334600**



Lack of stabilization

Lack of stabilization