

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD (APPEARS PLUMBER LIFT IS LEAKING).		
Corrective Action:	Conduct maintenance on equipment (REPAIR LEAKS), cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IMMEDIATE ACTION IS REQUIRED. SUBMIT PHOTOS OF CA REMEDIATION IN AN FIRR ASAP.		Date:
Type	OTHER		
Comment:	FIRR NOT FILED		
Corrective Action:	Submit Field Inspection Report Resolution form (FIRR) per rule 210.b. & 207. Include photos showing corrective actions resolved if possible.		Date: <u>02/14/2023</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Type: Gas Meter Run	# 1				
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.				
Corrective Action:					Date:
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date:
Type: Bradenhead	# 1				
Comment:	IS ACCESSABLE				
Corrective Action:					Date:
Type: Ancillary equipment	# 1				

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 277964 Lat: 37.183972 Long: -104.805048

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695105773, CA'S HAVE NOT BEEN ADDRESSED. THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION. IMMEDIATE ACTION IS REQUIRED.	beardslt	02/13/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403319970	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019755
695107581	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019740