

KODA Exploration LLC (10720)

Roaring Fork 14-28 Pad

(Location ID: 472992)

2022 Post-Reclamation Update

Reclamation Timeline:

- 05/17/2022 Recontoured Pad (See Exhibit A)
- 05/18/2022 – Drill Seeded Pad, Seeding Attempt 2 of 2. (No Photos available) Seeding Attempt 1 was for interim reclamation of 0.6 acres that occurred in 2021.
- 06/13/2022 – Repaired pad perimeter ripping for Stormwater Control (Exhibit B)
- 06/20/2022 – Post-Seeding Inspection, grass seeds germinating in drill seed rows. (Exhibit C & D)
- 09/11/2022 – Mowed growth on pad (Exhibit E)



5/17/2022 Roaring Fork 14-28 Recontouring Pad. Very windy so delayed top soil replacement and drill seeding until 5/18/22 (seeding attempt # 1 of 1. no photos).

Exhibit A



6/13/2022 Roaring Fork 14-28 Repaired pad perimeter ripping for stormwater control. Also repaired ripping at WHP Misty 2-7 (no photos).

Exhibit B



6/20/2022 Roaring Fork 14-28 Post seeding inspection (note grass seeds germinating in drill seed rows).

Exhibit C



6/20/2022 Roaring Fork 14-28 Post seeding inspection (note grass seeds germinating in drill seed rows).

Exhibit D



9/11/2022 Roaring Fork 14-28 Mowing pad. Also mowed WHP Misty 2-7 (no photos).

Exhibit E