

**Operator: CIVITAS NORTH LLC**  
**Location Name: Boomslang Fed 8-60 14A**  
**Loc ID: 454591**  
**Inspection: 696105736**



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**



**Exhibit E**



**Exhibit F**






**Exhibit G**



**Exhibit H**

**CA:** Tumbleweeds were observed throughout the location, with accumulations in and around equipment. Debris will need to be removed from location to comply with Rule 606.

**CA Resolution:** Weeds were removed from the equipment on 2/16/2023 to comply with Rule 606. Housekeeping tasks to manage the weeds throughout the location will continue. Once ground conditions improve, bare areas will be re-seeded and weeds will be sprayed/mowed as needed.




**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**

**CA:** Unknown red fluid observed at compressor skid on the north end of the location. Comply with Rule 912.b.(11). Chemical spills and releases shall be reported in accordance with applicable state and federal laws, including the Emergency Planning and Community Right-to-Know Act, the Comprehensive Environmental Response, Compensation, and Liability Act, the Oil Pollution Act, and the Clean Water Act, as applicable.

**CA Resolution:** Required skid cleanups to remain in compliance with Rule 912.b.(11) were completed on Friday, 2/17/2023.

**CA:** Crude oil was observed near load outlines on equipment. Control and contain spills/releases and clean up per Rule 912.a.

**CA Resolution:** Required skid cleanups to remain in compliance with Rule 912.a were completed on Friday, 2/17/2023.