

**COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**

NOV 09 1995 C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	1120 Lincoln St Denver, CO 80202 (303)892-2100
 00572237	
API No. 05-061 - 6140	LEASE NAME: USA BUTLER #2
LOCATION: NWNE10-19S-45W	OPERATOR: WESTERN OP.
DATE: 10-27-95	INSPECTOR: R. Vansickle
Insp. Type: ED	Insp. Status: TA
PA: Y N	Pass/Fail: P <input checked="" type="radio"/> F
	Viol.: <input checked="" type="radio"/> Y N
	NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	✓	
Pits (Reserve/Production) (Rule 902, 903, 904)	None.	
Fences (Rule 604.C.(3), 1003.A)	None.	
Tank Battery Equipment (Rule 604)	Pump unit.	
Fire Walls/Berms/Dikes (Rule 604)	N/A.	
General Housekeeping (Rule 603.G)	.OK.	
Spills (Oil/Water) (Rule 908)	None.	
Bradenhead (Rule 207)	-	
Drilling Well/Workover (Rule 315)	-	
Surface Rehabilitation (Rule 317)	-	
Miscellaneous	Tbg in hole.	✓

CORRECTIVE ACTION REQUIRED: MIT, Produce or plug.

Date Corrective Action Required By: 4-15-96. Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.