

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2023

Submitted Date:

02/24/2023

Document Number:

702500921**FIELD INSPECTION FORM**Loc ID 316458 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277678	WELL	PR	03/01/2021	OW	103-10570	S. B. LACY 13Y	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday, 02/23/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc (Scout Energy Partners) on the S.B. Lacy 13Y well, Location #316458, in Rio Blanco County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) High Priority/Density Habitat Districts.

Any Corrective Actions from previous Inspections are still applicable.

While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1. Chemical containment full

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 675-3700

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment. Containment is full.		
Corrective Action:	Conduct maintenance on containment equipment.		Date: 03/03/2023
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Electrical control panel		
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277678	Type:	WELL	API Number:	103-10570	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Submersible pump								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Compaction				
		Berms				
		Culverts				
		Ditches				
Compaction						
				Material Handling And Spill Prevention	Fail	Spill containment full
Berms						

Comment: Limited storm water inspection due to location being covered with snow.
Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.
Maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: Implement and maintain Best Management Practices (BMPs) for materials handling and spill prevention procedures and practices.

Date: 03/27/2023

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500924	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6032906