



00325667

ADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>121 - 05495</u>		LEASE NAME: <u>WFLU #10</u>	
LOCATION: <u>NESW 19-35-55</u>		OPERATOR: <u>H+R</u>	
DATE: <u>9-30-96</u>		INSPECTOR: <u>EBB Millay</u>	
Insp. Type: <u>CA</u>	Insp. Status: <u>PA</u>	PA: Y <input type="radio"/> (N) <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> (F) <input checked="" type="radio"/> Viol.: Y <input type="radio"/> (N) <input checked="" type="radio"/> NOV: Y <input type="radio"/> (N) <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	<u>H+R set cement plugs</u>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)	<u>H+R</u>	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	<u>incomplete</u>	
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Remove equipment and restore site within 6 months.

Date Corrective Action Required By: 3-30-97 **Date Remedied:**

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.