

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403355409

Date Received:

03/24/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

7 of 7 CAs from the FIR responded to on this Form

7 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10773

Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLC

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Smith, Sydney

303-910-4511

ssmith@fundareresources.com

Waggoner, Kyle

kyle.waggoner@state.co.us

Robinson, Taylor

taylor.robinson@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702700189

Inspection Date: 12/07/2022

FIR Submit Date: 12/20/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FUNDARE RESOURCES OPERATING COMPANY LLC

Company Number: 10773

Address: 5251 DTC PKWY STE 950

City: GREENWOOD VILLAGE State: CO Zip: 80111

LOCATION - Location ID: 428750

Location Name: Wildhorse Number: 02-0214H County: \_\_\_\_\_

Qtrqtr: Lot 4 Sec: 2 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.786140 Longitude: -103.952140

FACILITY - API Number: 05-123-00 Facility ID: 482443

Facility Name: Wildhorse 02 Number: \_\_\_\_\_

Qtrqtr: Lot 4 Sec: 2 Twp: 9N Range: 59W Meridian: 6

Latitude: 40.786140 Longitude: -103.952140

CORRECTIVE ACTIONS:

1 CA# 166660

Corrective Action: Secondary containment is not sufficiently impervious to contain spilled or released materials. Repair and maintain berms in accordance with Rule 603.a.(4).

Date: 01/20/2023

Response: CA COMPLETED

Date of Completion: 01/04/2023

Operator Comment: Berms Repaired In Accordance with Rule 603.a.(4). Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 166661

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. If the spill/release does not meet the reporting requirements of Rule 912.b., then Operator shall document cleanup efforts and provide documentation of the cleanup to Area EPS.  
  
If the spill/release meets the reporting requirements of Rule 912.b., then Operator shall report the spill/release of E&P waste and contact COGCC EPS staff per Rule 912.b.

Date: 12/22/2022

Response: CA COMPLETED Date of Completion: 12/15/2022

Operator Comment: Documentation Of Non-Reportable Spill Cleanup Has Been Submitted to Area EPS. Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 166662

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

Date: 12/27/2022

Response: CA COMPLETED Date of Completion: 12/16/2022

Operator Comment: Location Equipment Maintenance & Stainage Cleaned Up in Accordance with Rule 1002.f.(2).D. Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**4** CA# 166663

Corrective Action: Install sign to comply with Rule 605.g.

Date: 02/20/2023

Response: CA COMPLETED Date of Completion: 01/12/2023

Operator Comment: Signage Installed to Reflect Fundare Resources Company LLC as Current Operator to Comply with Rule 605.g. Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**5** CA# 166664

Corrective Action: Install sign to comply with Rule 605.g.

Date: 02/20/2023

Response: CA COMPLETED Date of Completion: 01/12/2023

Operator Comment: Signage Installed to Reflect Fundare Resources Company LLC as Current Operator to Comply with Rule 605.g. Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**6** CA# 166665

Corrective Action: Handle waste in accordance with Rule 906 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

Date: 12/27/2022

Response: CA COMPLETED

Date of Completion: 12/20/2022

Operator Comment: Location Equipment Maintenance & Stainage Cleaned Up in Accordance with Rule 906 and Rule 1002.f.(2).D. Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**7** CA# 166666

Corrective Action: Comply with Rule Rules 912.a.(1) and 912.a.(2).

Date: 12/23/2022

Pursuant to Rule 912.b.(6).B . Operator is required to submit a Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director.

Closure of this spill was due by September 24th, 2022. Operator shall submit a Form 27i for remediation of the spill within as soon as possible but no later than EOD December 23, 2022. Submit Form 19 Supplemental Report with any information not provided in previous Form 19's and for the purpose of requesting closure of Spill/Release 482443 as work will proceed under a Form 27.

Response: CA COMPLETED

Date of Completion: 12/14/2022

Operator Comment: Spill Discovered, Mitigated, Cleaned Up, Samples Pulled & Documentation Has Been Submitted in Compliance with Rule Rules 912.a.(1) and 912.a.(2). Please See Attached Photos

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melissa Parrish

Signed: \_\_\_\_\_

Title: Production/Compliance

Date: 3/24/2023 8:51:27 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403355447	Wildhorse 02-0214H 0214AH COGCC Corrective Actions Completed

Total Attach: 1 Files