

COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT



FAC# 188 API# 121 05468 0 INSPECTOR L. Robbins DATE 9/21/87
 WELL NAME WEST FORK UNIT 14 TYPE E SITE INSPECTION X
 FIELD 91128 WESTFORK WITNESS MIT _____
 OPER 8005 BERRY ENERGY INC
 LOCATION SESW 19 3.0S 55.0W 6



00325871

MAX PERMITTED PRESS 1310 PSI DATE LAST INSPECTION 09/09/86 OUTCOME A
 LAST REPORTED PRESS PSI 00/00 DATE LAST MIT 00/00/00
 WELL RESTRICTIONS 5/12/87 APPRV'D TA - MUST REPORT STATUS EVERY 6 MOS
 REMEDIAL ACTION
 COMPLETION TYPE CD

TUBING PRESSURE

ZONE JSND

MIT _____ INJECTING _____ PSI

MIT _____ NOT INJECTING St PSI

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

TOP 4901
 BOT 4906

P E R F S

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

MIT
 PACKER
 DEPTH _____

CASING
 SIZE 8 5/8
 DEPTH 286

SIZE 5 1/2
 DEPTH 4901

SIZE /
 DEPTH

SIZE /
 DEPTH

PACKER 4875

LINER
 TOP
 SIZE
 DEPTH

PBTVD
 TVD

ACCEPTABLE X NOT ACCEPTABLE _____

REMARKS: Flowline has been disconnected
from wellhead making it inoperable.
Well is to remain shut-in until
it passes an mit. y Robbins