



SUNDRY NOTICE

This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (back of this form).

1. OGCC Operator Number: 36980	4. Contact Name & Phone
2. Name of Operator: H & R Well Services, Inc.	Dave Rebol
3. Address: 17509 County Road 14	No: 970-867-9007
City: Ft. Morgan State: CO Zip: 80701	Fax: 970-867-8374
5. API Number: 05-121-5496	6. OGCC Lease No: 54853
7. Well Name: WFU	Number: 9
8. Location (QtrQtr, Sec, Twp, Rng, Meridian): NW SW 19-3S-55W	
9. County: Washington	10. Field Name: Westfork
11. Federal, Indian or State lease number:	

Complete the Attachment Checklist

	Oper	OGCC
Survey Plat		
Directional Survey		
Surface Equipment Diagram		
Technical Information Page		
Other		

General Notice

12.

Change well name from _____ to _____ Effective Date: _____

Change of location from _____ Attach new survey plat. to _____

Abandoned Location. Is site ready for inspection? Yes No Effective Date: _____
Was location ever built? Yes No Permit No: _____

Well first shut in or temporarily abandoned _____ Notice of continued shut-in status.
Has production equipment been removed from site? Yes No
MIT required if shut in longer than two years. Date of last MIT: _____

Well resumed production on _____

Request for Confidential Status (6 months).

Final reclamation will commence approximately on _____

Final reclamation is completed and site is ready for inspection. Attach technical page describing final reclamation procedures per Rule 1000c.4. *11/10/96*

Change of Operator (prior to drilling). Effective Date: _____ Plugging bond: Blanket Individual

Spud Date _____

Technical Engineering/Environmental Notice

13.

Notice of Intent Approximate Start Date: _____ Report of Work Done Date Work Completed: _____

Details of work must be described in full on Technical Information Page (Page 2 must be submitted).

<input type="checkbox"/> Commingle Zones <input type="checkbox"/> Intent to Recomplete (Submit Form 2) <input type="checkbox"/> Change Drilling Plans <input type="checkbox"/> Reservoir Stimulation <input type="checkbox"/> Perforating/Perfs Added Gross Interval Changed? <input type="checkbox"/> Y <input type="checkbox"/> N	<input type="checkbox"/> Request to Vent or Flare <input type="checkbox"/> Repair Well <input type="checkbox"/> Convert Well to Injection (In an Approved Secondary Project) <input type="checkbox"/> Additional Source Leases for Water Disposal Well <input type="checkbox"/> Other: _____	<input type="checkbox"/> E&P Waste Disposal <input type="checkbox"/> Beneficial Reuse of E&P Waste <input type="checkbox"/> New Pit <input type="checkbox"/> Landfarming <input type="checkbox"/> Status Update/Change of Remediation Plans for Spills and Releases
---	--	---

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name Dave Rebol
 Signed [Signature] Title: V.P. Date: 11/10/96

OGCC Approved: [Signature] Title: SR. PETROLEUM ENGINEER Date: DEC 16 1996
 O & G Cons. Comm.

CONDITIONS OF APPROVAL, IF ANY:

Fill out Form 6

** Please submit final P+A on a Form 6.*

1. Operator Number: 36980	2. API Number: 05- 121-5496
3. Name of Operator: H & R Well Services, Inc.	
4. Well Name: WFU	Number: 9
5. Location (QtrQtr, Sec, Twp, Rng, Meridian): NW SW 19-3S-55W	

FOR OGCC USE ONLY

RECEIVED
NOV 22 1986

ET	OE	PR	ES
----	----	----	----

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within thirty (30) days of work completed as a "subsequent" report and must accompany Form 4, page 1.

6. **DESCRIBE PROPOSED OR COMPLETED OPERATIONS**

Set CIBP @ 4900' & 2 sxs cement.
Pull 5½" casing from 1300'
40 sxs cement @ base of surface 9-5/8 from 240' up
10 sxs surface plug
Cut off 4' below ground level and weld on cap
Restore surface location