

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2023

Submitted Date:

04/04/2023

Document Number:

696204813

FIELD INSPECTION FORM

Loc ID 323855 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

Findings:

- 9 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		hsirvent@locinoil.com	
		dbenedict@locin.energy	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210996	WELL	SI	06/01/2020	GW	045-06754	FEDERAL 33-8	RI
323855	LOCATION	AC			-	FEDERAL-67S104W 33SENE	RI

General Comment:

On 3/31/2023, Reclamation Specialist Trujillo inspected Locin Oil Corporations' FEDERAL #33-8 Location in Garfield County, Colorado.

The following compliance issues were observed during this inspection:
-Tank signage/labeling
-Unmarked Anchors

Refer to the "Location", "Reclamation" and "stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Signage at tank posted with incorrect Operator information.		
Corrective Action:	Comply with Rule 605.h	Date:	05/04/2023

Emergency Contact Number:			
Comment:	970-858-7546/911		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog Panelling		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	BV PLASTIC		,
Comment:	See "signs/marker" for singage requirements				
Corrective Action:		Date:			

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No			
--------	--	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Large empty rectangular area for detailed notes or data entry.

Inspected Facilities

Facility ID: 210996 Type: WELL API Number: 045-06754 Status: SI Insp. Status: RI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Records show well status of "Shut In" since June 2020. Form 5B 403291617 on file per Inactive Well requirements.

Operator submitted Form 4 #403062363 requesting approval of alternative MIT based on bradenhead testing. Sundry was approved with conditions requiring annual bradenhead tests reported on a Form 17.

Last test date 5/25/2022; 2023 bradenhead test required no later than 5/25/2023

Corrective Action: _____ Date: _____

Facility ID: 323855 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment Inspection #693805274 observed anchors missing required marking.
Only two anchors were observed on the west and northwest end of the Location; unclear if remaining anchors have been removed, or have been covered by sediment or vegetation.
Anhors remain unmarked. CA has not been addressed and remain applicable. If anchors are no longer necessary on the Location, they are required to be removed per Rule 606.

Corrective Action Install proper guy line markers per Rule 1003.a, or remove per Rule 606.

Date **11/30/2022**

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment No immediate reclamation issues observed; noxious weeds not observed at time of inspection. Location Federal surface; final passing of reclamation subject to Federal approval.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: BMPs to stabilize the access road and Location show signs of degradation. Maintenance advised prior to failure of erosion, degradation and tracking control BMPs.						
Corrective Action: <input type="text"/>						Date: <input type="text"/>
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403365228	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072284
696204814	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072275