

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403371539

Date Received:
04/12/2023

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204837

Inspection Date: 04/05/2023

FIR Submit Date: 04/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334732

Location Name: ENCANA-67S95W Number: 21NWNW County: _____

Qtrqr: NWN Sec: 21 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.429360 Longitude: -108.009200

FACILITY - API Number: 05-045- -00 Facility ID: 334732

Facility Name: ENCANA-67S95W Number: 21NWNW

Qtrqr: NWN Sec: 21 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.429360 Longitude: -108.009200

CORRECTIVE ACTIONS:

2 CA# 169116

Corrective Action: Comply with Rule 606.

Date: 05/06/2023

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: All equipment is in regular use. The rig heater is something we use during the winter/spring and is staged out in the field during the season. In the summer, once it is no longer needed, it will be moved offsite. The blade and water truck are used daily to maintain nearby access roads and the working surface.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC Decision is "not approved"; the storage of the rig heater on Location is permitted. Location is not a storage yard; the Corrective Action requiring compliance with Rule 606 regarding the improper storage of equipment and/or vehicles on the Location remains applicable.

COGCC Supervisor: COGCC Decision is "not approved"; the storage of the rig heater on Location is permitted. Location is not a storage yard; the Corrective Action requiring compliance with Rule 606 regarding the improper storage of equipment and/or vehicles on the Location remains applicable.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 4/12/2023 1:44:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403371539	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files